FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

1	Name of the Officer	ELDHO PAULOSE
2	Name of the School	JAIRANI PUBLIC SCHOOL KALIYAR
3	Location with name of Education District/ Sub. District	THODUPUZHA ,KALIYAR
4	Classification of Building as specified in column 4 of the application for fitness certificate and size.	Permanent Building
5	Period for which the certificate is issued	2021-2022
6	Nature of defects, if any	
	Foundation and basement	
	b) Superstructure	PCC FRAMED STRUCTURE 1) GROUND FLOOR CLASS ROOM-6.5X6.15X3.6 (5 NOS) OFFICE ROOM-6.5X6.2X3.6 staff room,principle rool 2)FIRST FLOOR CLASS ROOM-6.5X6.2X3.6 (5 NOS) LIBRARY,COMPUTER-6.55X6.2X3.6 3)SECOND FLOOR CLASS ROOM-6.3X6.55X3.6 (6 NOS) 6.17X6.55X3.6 DIGITAL CLASS ROOM-6.17X6.55X3.6
	c) Doors and Windows	
	d) Wood work wrought and put up	-
	e) Roof	
	f) Flooring	-
-	g) Miscellaneous (Cracks, etc.) Any major defects noticed which will render the	
7	building unsafe in any manner	
8	Whether maintenance works have been done properly	
9	Whether the structure is sound or not for conducting classes	Yes, The Structures are Sound under Normal weather Condi

The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure Note: 1 of flood etc.

Note: 2 Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate

CERTIFICATE

JAI RANI PUBLIC SCHOOL KALIYAR, IDUKKI (Dist.)

Certified that the school building was inspected by me on30/10/2021..... And found to be fit to CERMICA - 685 607 classes, for the period 2021-2022...... for the reasons stated above.

Place: Vannappuram Date: 30-10-21

ASSISTANT ENGINEER LID & EW SECTION YANNAPPURAM GRAMA PANCHAYATH